

2 March 2009

To Whom It May Concern

363 George Street is a landmark 33 storey office tower in the Sydney CBD it had a CCTV system that was failing on a regular basis. This was due to the age of the equipment & quality of the installation. SSE installation were maintaining the system, but the system used to break down more frequently as time went on and needed to be upgraded.

The tenants require video footage of incidents that happen from time to time and we were not always able to supply this footage, due to the poor performance of the existing CCTV system. This was not satisfactory to the building owners, upper management and the tenants.

We needed the latest in technology that would be reliable and carry us through for the next 10 years. SSE Installations was able to provide us with that solution, as well as the education and implementation of designing a system that is easily upgraded, technically and financially in the future.

SSE Installation supplied a professional CCTV system with a quality installation that is very user friendly and an effective surveillance system. The design and layout of the installation answers all of the building and tenants needs for the present and immediate future.

Yours sincerely
CB Richard Ellis Pty Ltd


Felix Rodrigo
Senior Engineering Manager – Asset Services